

UNSCANNABLE ITEMS NOT INCLUDED IN THE AIRWORTHINESS DIRECTIVE (AD) DMS DOCKET

DMS Docket Number: FAA-2004-18038

Directorate Identifier: 2004-NE-01-AD

Name/ Description of Unscannable Item

Textron Lycoming Service Bulletin No. 0002, Revision 2, dated March 6, 1989

Honeywell International Inc. SB No. T5313B/17-0020, Revision 7, dated March 15, 2001

Honeywell International Inc. SB No. T5313B-0125, dated March 15, 2001

Honeywell International Inc. SB No. T5317-0125, dated March 15, 2001

Honeywell International Inc. SB No. T53-L-13B-0020, Revision 3, dated October 25, 2001

Honeywell International Inc. SB No. T53-L-13B-0125, dated April 5, 2001

Honeywell International Inc. SB No. T53-L-13B/D-0020, Revision 2, dated November 25, 2002

Honeywell International Inc. SB No. T53-L-13B/D-0125, dated April 5, 2001

Honeywell International Inc. SB No. T53-L-703-0020, Revision 2, dated November 25, 2002

Honeywell International Inc. SB No. T53-L-703-0125, dated April 5, 2001

SERVICE INFORMATION MAY BE EXAMINED AT:

National Archives and Records Administration (NARA).

For information on the availability of this material at NARA, call 202 741 6030; or go to:

<http://www.archives.gov/federal-register/cfr/ibr-locations.html>

or

**Federal Aviation Administration
New England Region
Office of the Regional Counsel
12 New England Executive Park
Burlington, MA 01803**

by appointment, between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays